



[Portal](#) > [Knowledgebase](#) > [High availability](#) > [Support for VRRP with rfc3768 using i40e NICs](#)

Support for VRRP with rfc3768 using i40e NICs

Dmitriy Eshenko - 2021-10-06 - 0 Comments - in High availability

In case if VRRP used on NICs based on i40e driver, like Intel X710/X722 with rfc3768-compatibility necessary to disable pruning sources. The best way is to use `/config/scripts/vyos-postconfig-bootup.script` and add the following command:

```
ethtool --set-priv-flags ethX disable-source-pruning on
```